



REMOVE COVER (13), AND BEHIND JOINT (26 & 28) ARE THE MICRO BASKET FILTERS

NOTE: THIS IS TYPICAL OF A 150 HPDI WHICH HAS ONE PUMP AND OPERATES AT 750PSI. I KNOW THE 300 HPDI'S HAVE TWO PUMPS AND OPERATE AROUND 1000PSI. SO ON A TWO PUMP SYSTEM YOU WOULD HAVE 4 FILTERS TO REPLACE.

MICRO BASKET FILTERS ARE PRESSED INTO PUMP HEAD ONE ON THE INLET AND ONE ON THE OUTLET